

4520 Hampton Road – Clemmons, NC 27012 – (336) 766-9036

QUALITY ALERT • 04142023


Date:04/14/2023

To: Suppliers of Assembled Components

Subject: Staking Operations

This alert is to raise awareness of a failure that occurred at a supplier site during an assembly process.

A relief valve purchased from a supplier was found to have been assembled without the technician completing the staking operation required in their work instructions. This resulted in a leak failure of the component (image below) and a potential release of non-conforming product shipped to a customer.



This condition was internal and could not be detected by inspection of the finished assembly. Suppliers are urged to review their Shop Travelers/ Operation Sheets to ensure there is a separate sign off for staking operations and verification of the process.

Franklin E. Hurak Supplier Quality Engineer Triumph Actuation Systems, LLC – Clemmons Phone# 336-714-8237 fhurak@triumphgroup.com